

DCC

Versailles, le 18/05/2009.

INFO-TECH CITROËN Racing C2 R2 MAX N° 17A/09.

Subject : Engine loom, motorised throttle connector .

Dear Customers,

An error was done in the last *infotech N°17/09*, May the 5th, 2009.

The tie rap on throttle body side (shown on pictures below) was tightened below the locking pin of the throttle connector. This way, a disconnection of the connector was potentially possible.

So, we suggest you to assembly the tie rap over the connector locking pin, as shown on pictures below :



Tie rap assembly over the locking pin

Thank you for your attention.