

DCC/SB

Versailles le 20/02/2008.

INFO-TECH CITROËN Sport C2 R2 MAX N° 02/08

Subject : Front brake discs.

Dear Customers,

Bobbins screws have to be tightened to 3.mkg, without Loctite.

The assembling sheet has been modified about this new torque, you can recognize it by the revision number (2), as shown on the picture below.



Thank you for your attention, and your understanding.

S. BARRAUD, le 20/02/08