

DCC/SB

Versailles le 03/06/2008.

INFO-TECH CITROËN Sport C2 R2 MAX N° 07/08.


Sujet : Clutch disk, pads.

Dear Customers,

A defect has been discovered on C2R2 / MAX clutch disks (part number 1C1143317A). Please pay attention on informations below :

A - Brand new disk :

If you have a **brand new disk, never assembly** on your engine, and you can see **F23G7847** number written on it (as shown on pictures below), please send it back to us. A brand new one, from a different serial will be sent to you as soon as possible.



Thank you to send it back at the following mailing address and attention :

CITROËN Sport
A l'attention de Mr Samuel BARRAUD
19, Allée des Marronniers
78035 VERSAILLES Cedex

B - Used disk :

If you have one or more clutch disks, with pads partially or completely missing (as shown both pictures below), and if the pads thickness is more than **6.6mm**, you can also send it to us to the mailing address written on top of the document. A brand new one will be also sent to you.

Be carefull, this « warranty » will be ok only if parameters below are respected :

- One or many pads broken.
- One or many pads missing.
- Expertise sheet thoroughly completed (in attached file of the mail), without information missing.
- Thickness between two pads over than **6.6 mm**.

Pads defects examples :



Nota : CITROËN Sport reserve the right to refuse a warranty if the state of a disk is doubtful, pads totally used, or questionable warmed marks on it.

Thank you for your attention.

S. BARRAUD, le 02/06/08