

DCC

Versailles, le 12/03/2009.


INFO-TECH CITROËN Racing C2 R2 MAX N° 14/09.

Subject : Engine fan bracket, Length screw reduction.

Dear Customers,


In case of a front crash, a screw of the engine fan bracket may damage the engine oil filter.

I -Risk location :



II - Low screw modification on the part réf OB1263097A :

We recommand you to reduce the lenght of the cooling fan bracket screw, as shown on the picture below :



Thank you for your attention.

JP GAUDUCHON, le 12/03/09