


Subject : Body, rear « quick release » hobby.




Dear Customers,

Regarding a technical request by the F.I.A., the quick release system of the rear hobby is not in accordance with the technical rules of the R group.

This way, we suggest you to remove the release side (as shown on pictures below), and to replace it by the standard system.

I - Removing of the quick release hobby hinge (part number 2K7C62634A), hobby side :



II - Assembly of the standard hinge :



Thank you for your attention